

## **Data Sheet**

## S/X-BAND PULSED FERRITE PHASE SHIFTER

HPM-05-SX-PPS-1XX



## Technical Data

Туре		HPM-05-SX-PPS-1XX
Frequency	GHz	2.850 - 3.005 / 9.295 - 9.305
Insertion Loss	dB	< 0.05
Power Handling	W	Up to 25 MW/p and 6 kW/avg
Switching speed	PRF	300 Hz
Phase tuning	angle	crowave Solutions 0-440°
Phase step	Solu	mbH Microwave Solutions GmbH rowave Solutions GmbH Micro≪0.5° tions GmbH Microwave Solutions GmbH
Waveguide size	tWR <sub>18</sub> G	ave Solutions GmbH Microwave Solu- mbH Microwave Solutions Gm284/90rowave s GmbH Microwave Solutions GmbH
Flanges	GmbH Micr	Solutions GmbH Microwave Solutions owave Solutions GmbH MAllFlanges on requesting pwaye Solutions GmbH Microwave Solutions
Leakage rate	mbar*l/s	owave Solutions GmbH Microwave Solutions owave Solutions GmbH Microwave Solutions owave Solutions GmbH Microwave Solu-
Material	tions Gm Solution	oH Microwave Solutions GmbH Microwave ns GmbH Microwave SolutionOngequest nve Solutions GmbH Microwave Solutions
Finish	GmbH	Microwave Solutions GmbH Microwave tions GmbH Microwave Solu On request bH
Operating Pressure		Solutions GmbH Microwave Solutions GmbH Micro 4 bar absolut SF6 Solutions GmbHUHV 10^-9 mbar*1/s
Operating Temperature		0°C to 35°C

## Please Note:

As a result of more stringent legal regulations and judgements regarding product liability, we are obliged to point out certain risks that may arise when products are used under extraordinary operating conditions.

Extraordinary operating conditions, such as heavy icing or exceptional dynamic stress (e.g. strain caused by oscillating support structures), may result in the breakage of a mast mounted device or even cause it to fall to the ground

These facts must be considered during the site planning process.

The installation team must be properly qualified and be familiar with the relevant national safety regulations.

The details given in our data sheets must be followed carefully when installing the devices and accessories.

Terminate unused inputs with a suitable 50-Ohm load.

Any previous datasheet issues have now become invalid.

Page 2 of 2